

WASHING SYMBOLS

COTTON AND FLAX

WASHING

Use appropriate bath/linen ratios for cotton and linen so as to avoid cotton waste at the edge of the items or even a premature degradation.



- Without hypochlorite (bleach), in water at a maximum temperature of 80°C



- With hypochlorite (bleach), in water at a maximum temperature of 40°C

Fabric will be destroyed if the temperature is more than 40°C.

- Never use chlorine at more than 40°C so as not to destroy fabric.



- Indanthrene colours used are resistant to chlorine and to perborate contained into the detergents.

- Detergents containing perborate are preferable to those containing chlorine because they can be used also with higher temperature.

DRYING



After washing, before drying, make sure that the linen has been perfectly rinsed so as to avoid the yellowing of white items.

- In a dryer (even tumble-dryer) with no temperature limits.

IRONING

Fabrics must be ironed with a residual humidity of about 20%.

Flax or union flax must be ironed with higher humidity than cotton (about 30%), more slowly and with greater ironing pressure.



- Ironing at a maximum temperature of 200°C, with damp fabric.

UNION COTTON-POLYESTER AND 100% POLYESTER

WASHING



- Without hypochlorite (bleach), in water at a maximum temperature of 60°C.
Rinse out at gradually decreasing temperature (for slow cooling down).
Reduced centrifugation.



- With hypochlorite (bleach), in water at a maximum temperature of 40°C.
Fabric will be destroyed if the temperature is more than 40°C.

- Never use chlorine at more than 40°C so as not to destroy fabric.



- Indanthrene colours used are resistant to chlorine and to perborate contained into the detergents.

- Detergents containing perborate are preferable to those containing chlorine because they can be used also with higher temperature.

DRYING



- Tumbler drying with remaining humidity of 20-50%, maximum temperature of 120°C and at lower load.

IRONING



- Ironing at a maximum temperature of 150°C. Put a damp cloth in between.

WASHING SYMBOLS

TREVIRA CS FLAME RETARDANT LINEN 100% POLYESTER F.R.

WASHING

Use appropriate relation bath/linen for the fabric Trevira CS Flame Retardant in order to avoid pleats difficult to take off.



- Delicate washing with cheap program at lower load with detergents on anionic basis at maximum temperature of 40°C.
- Dry-clean with perchlorethylene is allowed.



DRYING

- Tumbler drying with remaining humidity of 20-50%, maximum temperature of 120°C and at lower load.



IRONING

- Iron at a maximum temperature of 110°C with remaining humidity of 40-50%.



BLANKETS AND TABLE FELT

100% WOOL - 80% WOOL / 20% POLYAMIDE

WASHING

- Dry-cleaning (with perchloroethylene or similar).



DRYING

- Doesn't stand tumble-drying.



IRONING

- Ironing at a maximum temperature of 150°C. Put a damp cloth in between.



100% ACRYLIC - 50% WOOL / 40% ACRYLIC / 10% COTTON

WASHING

- Washing at temperature of 40°C with water and neutral-soap temperature of based detergents.



DRYING

- In dryer at low temperatures.



IRONING

- Ironing at a maximum temperature of 110°C. Put a cloth in between.



RIVOLTA CARMIGNANI